



. .

Heat Boxes 1, 2, 3 (with Reference Points)









ICMH Mitigation

F16.4






FIG. 5




Welding System with Weld Hand Leannier

F16.6




F16.7




Micrographs Comparing Ferrite Size and Distribution for NM Cladding with Type 316L +1Pd Filler, 800 X Magnification. (A) Mechanized ICMH Cladding, (B) Manual Cladding

シ い う し




Micrographs Comparing Ferrite Size and Distribution for NM Cladding Magnification. (A) Mechanized with Type 308L +1Pt Filler, 800 X ICMH Cladding, (B) Manual Cladding

F1G. 9




ID/OD Residual Stress (Clad)
FIG. 10A



ID Residual Stress (no clad)

FIG. 10 B



ID Residual Stress (clad)

FIG. 10C